

# **Irrigation Infrastructure Renewal Projections - 2013/14 to 2046/47**

Report - Lower Lockyer Tariff Group



## © Queensland Bulk Water Authority 2012

This document is and shall remain the property of Queensland Bulk Water Authority. The document may only be used for the purposes for which it was prepared. Unauthorised use of this document in any form whatsoever is prohibited.

### **Document Status**

Version	Date	Author	Reviewed	PCG Approval
1	20/4/12	AL/GH	MD	
2	23/4/12	GH	MD	
3	19/9/12	GH	MD	



# Contents

1.	Intro	oductio	n	4
2.	Ass	et Infor	mation	5
	2.1	Irrigati	ion Infrastructure	5
	2.2	Releva	ant Asset Information	5
3.	Pro	jections	3	7
	3.1	Summ	nary	7
	3.2	Signifi	cant Projects	7
	3.3	Addition	onal Commentary	9
Ta	ble Ir	ndex		
	Tabl	e 1	Summary of Irrigation Infrastructure	5
	Tabl	e 2	Significant Projects	7
	Tabl	e 3	Summary of Renewal Projections	8

# **Appendices**

- Water Supply Scheme Schematic
- В Renewal Projections



# 1. Introduction

Seqwater owns and operates the following seven irrigation schemes:

- Central Lockyer WSS;
- Lower Lockyer WSS;
- ▶ Logan River WSS;
- Mary River WSS;
- Cedar Pocket WSS;
- Warrill Valley WSS; and
- Central-Brisbane WSS.

Segwater also owns and operates a distribution system, the Morton Vale Pipeline.

There are nine tariff groups associated with these schemes.

To assist with the determination of price paths, a forecast of future renewal expenditure is required at the individual tariff group level.

The renewal projections have been developed, in accordance with the scope and methodology separately documented in the Methodology report. The projections have been developed in separate reports, one for each tariff group.

This report outlines the projections for the Lower Lockyer Tariff group. It should be read in conjunction with the Methodology report.



# 2. Asset Information

### 2.1 Irrigation Infrastructure

A summary of Seqwater's irrigation infrastructure facilities and assets is provided in **Table 1** below.

Table 1 Summary of Irrigation Infrastructure

WSS Scheme	Tariff Group	Dams	Weirs	Off-Stream Storage	Other Key Assets
Lockyer	Lower	NA	Brightview Weir, Buaraba Creek Weir, O'Reilly Weir, Potters Weir, Sippels Weir	Atkinson Dam	Buaraba Creek Channel, Brightview Channel Rising Main, Buaraba Creek Supply Pipeline, Brightview Channel, Buaraba Creek Diversion Channel, Gauging Stations, Observation Bores, Atkinson Pump Station, Seven Mile Lagoon Diversion Channel, Flowmeters

A schematic drawing of the scheme is provided in Appendix A.

#### 2.2 Relevant Asset Information

The following existing information was reviewed and where relevant, utilised to develop the renewal projections:

- Asset Register;
- Annual, 5 Year and Comprehensive Dam Safety Reviews and Assessments;
- ▶ Draft WSS 20 Year Programme of Work 2008/09 2028/29;
- 2011 Site Safety Assessments;
- Extracts from Financial Asset Register;
- 2009 Asset Valuation Cardnos;



- 2010 Asset Valuation Dams & Weirs Cardnos;
- Atkinson Dam Facilities Asset Management Plan (FAMP) 2012; and
- ▶ Business Case Irrigation Customer Meters Renewal (SM 12/13 02).



# 3. Projections

### 3.1 Summary

A summary of the renewal and refurbishment projections for the period 2013/14 - 2046/47 is provided in Table 3.

Further details are provided in Appendix B.

It should be noted that all values are in \$2012-13.

## 3.2 Significant Projects

A list of projects that come under one of the following categories are outlined in Table 2 below:

- ▶ Scheduled between 2013/14 and 2016/17 financial years and having a project value greater than the average project value for that period; and
- A project that has an impact on the annuity of greater than 10%<sup>1</sup>.

Table 2 Significant Projects

Asset	Description of Work	Timing of Work	Project Value	Signif.*
Potters Weir	Rehabilitation to repair scour bypass of weir	2013/14	\$60k	HAV
Sippels Weir	Rehabilitation to repair scour bypass of weir	2013/14	\$72k	HAV
Brightview Weir	Rehabilitation of embankment	2043/44	\$2070	IA
Brightview Channel	Desilting	2016/17	\$66k	HAV
Brightview Channel	Replacement of fencing (50% shared with adjacent landowners)	2013/14	\$47k	HAV
Water Meters	Water Meter Renewal Program	Annually, commencing 2013/14	\$870k over 33 years	HAV Ref. Footnote

Notes: \*Significance: HAV – Higher than Average Value (for period from 2013/14 to 2016/17) IA – Project was assessed in April 2012 (refer Footnote 1 below) as having an impact on the annuity of greater than 10% (refer Section 3.3 for commentary).

Filename: Seqwater\_IrrigRen\_Tariff Group Summary\_LLO\_Ver 3\_Sept12

<sup>&</sup>lt;sup>1</sup> The impact on annuity was assessed in April 2012 when version 2 of this report was produced. At that time, the water meter renewal program had not been fully developed and included in the assessment. An updated assessment of impact has not been undertaken in updating this current version 3 of the report



Table 3 Summary of Renewal Projections

Parent Asset								Expend	liture Fo	orecast	Each Ye	ar (\$k)						
		2013/14	2014/15	2015/16	2016/17	2017/18	2018/19	2019/20	2020/21	2021/22	2022/23	2023/24	2024/25	2025/26	2026/27	2027/28	2028/29	2029/30
Atkinson Dam		40	20	-	-	60	15	30	125	22	21	21	-	-	-	45	-	45
LL Distribution		206	-	-	66	43	141	-	10	78	349	106	-	-	93	77	141	-
Water Flowmeters		158	158	22	22	22	22	22	22	22	16	16	16	16	16	16	16	16
	Total	404	178	22	88	125	178	52	157	122	386	143	16	16	109	138	157	61

## NB. Cell contents in this sheet are commonly linked to cells in Renewals sheet

Parent Asset								Expend	diture F	orecast	Each Ye	ar (\$k)						
		2030/31	2031/32	2032/33	2033/34	2034/35	2035/36	2036/37	2037/38	2038/39	2039/40	2040/41	2041/42	2042/43	2043/44	2044/45	2045/46	2046/47
Atkinson Dam		112	217	5	-	-	10	-	66	-	-	154	-	21	31	-	-	-
LL Distribution		59	66	94	139	-	-	66	83	187	15	2	210	82	3,137	28	46	66
Water Flowmeters		16	16	16	16	16	16	16	16	16	16	16	16	16	16	16	16	16
	Total	187	299	115	155	16	26	82	165	203	31	172	226	119	3,184	44	62	82



## 3.3 Additional Commentary

Commentary on projects that have a higher than average project value includes:

- Repair of scour bypass of Potters Weir by installing sheet pile wall to stop significant leaking.
- Repair of scour bypass of Sippels Weir by installing sheet pile wall to stop significant leaking.
- De-silting of Brightview Channel including repair of drainage benches to ensure efficient transfer of water.
- ▶ Replacement of 4km of boundary fencing along Brightview Channel. Cost is 50% of total cost due to cost sharing with adjacent landowners.

The following commentary is provided on the Brightview Weir embankment rehabilitation project listed in Table 2 as having an annuity of greater than 10%:


The renewal work has been forecasted for when the embankment is considered likely to reach the end of its useful life based on its age and typical useful asset life. The cost estimate shown is based on the replacement cost from the asset valuation data. The renewal work will most likely comprise of rehabilitation of the embankment and be less than the cost of replacement.

For the forecasted renewal expenditure between 2013/14 and 2016/17, values were compared with Sunwater's renewals projections which were the basis of the SunWater irrigation prices for 2006/07 to 2010/11. When excluding the water meter upgrade costs which will be excluded from the annuity, it was noted the total value of Seqwater's renewal forecast was approximately 130% of Sunwaters. The difference is believed to be primarily due to:

- Seqwater projections being based on more up-to-date information.
- ▶ Seqwater projections include more expenditure on distribution infrastructure including the repair of Potters and Sippels Weirs.



# Appendix A Water Supply Scheme Schematic





# Appendix B Renewal Projections

Parent Asset	Asset Details Asset Description	Works	Renewal Detai Comments	ls Costing Source	2013/14 20	014/15 20	015/16 20	16/17 20	17/18 20:	18/19 20	19/20 20	020/21 20	021/22 20	022/23 20	023/24 20	024/25 20	25/26 20	026/27 20				t Each Ye 30/31 203		32/33 203	3/34 203	4/35 2035	/36 2036	6/37 203	37/38 203	8/39 203	9/40 204	10/41 204	11/42 204	12/43 204	43/44 204	14/45 204	15/46 2046
Atkinson Dam	Office Building	Description Replace		Static Asset Data																			110														
Atkinson Dam Atkinson Dam	General Storage	Replace	-	Static Asset Data Static Asset Data		-	-	-			-		-		-					-	-	-	47		-		-	-	-	-	-			-		-	-
Atkinson Dam	Project Storage	Replace	_	Est	_	_	_	_	_	_	_	_	_	_	_	_	_	_	_	_	_	_	30	_	_	_	_	_	_	_	_	_	_	_	_	_	_
Atkinson Dam	Core Shed/Storage	Replace	_	Est	_	_	_	_	_	_	_	_	_	_	_	_	_	_	_	_	_	_	30	_	_	_	_	_	_	_	_	_	_	_	_	_	_
Atkinson Dam	Fencing	Replace		Buss Case 2012	10	_	_	_	_	_	_	_	_	_	_	_	_	_	_	_	_	_	-	_	_	_	_	_	_	_	_	_	_	_	10	_	_
Atkinson Dam	Outlet Works To Pstn	Refurbish	Refurbish metal items		-	-	_	_	_	-	_	10	_	_	_	_	_	_	_	_	_	_	_	-	_		10	_	_	-	_	_	_	_	-	_	_
			and install kickboards around handrails																																		
Atkinson Dam	Bulkhead Gate	Replace	_	20yr PW	_		_	_	5	_	_	_	_	_		_	_	_	_	_		_	_	5	_	_	_	_	_	_	_	_	_	_	_	_	_
Atkinson Dam	Monorail & 1 Tonne Crane	Replace		DW Val 2010	-	_	_	_	-	_	_	_	_	_	_	_	_	_	_	_	_	_	_	-	_	_	_	_	_	_	_	11	_	_	_	_	_
Atkinson Dam	Trash Screens	Replace	-	DW Val 2010	_	_	_	_	_	_	_	_	_	_	_	_	_	_	_	_	_	_	_	_	_	_	_	_	_	_	_	116	_	_	_	_	_
Atkinson Dam	Trash Screens	Replace	_	20yr PW	_	_	_	_	-	-	-	-	-	-	_	-	_	-	-	-	45	-	_	_	_	-	-	-	_	-	-		-	_	-	-	_
Atkinson Dam	Valve, 914Mm Butf	Replace	-	DW Val 2010	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	27	-	-	-	-	-
Atkinson Dam	Valve, 914Mm Butf	Refurbish	Assess in advance and then refurbish as required	20yr PW	-	-	-	-	10	-	-	-	-	-	-	-		-	10	-	-	-	-	-	-	-	-	-	10	-	-	-	-	-	-	-	-
Atkinson Dam	Valve, 914Mm Butf	Refurbish	Gate Valve No1 - OK	20yr PW		-	-	-	-	-	-	-	22	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-
Atkinson Dam	Access Roads And Carpark	Refurbish	Roadwork - seal road	FAMP	-	-	-	-	10	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-
Atkinson Dam	Spillway Control Structure	Refurbish	Sluice Gate 1 Assembly Gate unable to be opened. Gear box and gate to be repaired.	- FAMP	15	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-
Atkinson Dam	Spillway Control Structure	Refurbish	Sluice Gate 2 Assembly Gate unable to be opened. Gear box and gate to be repaired.	- FAMP	15	-	-	-	-	-	-	-	-	-	-	-		-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-
Atkinson Dam	Spillway Control Structure	Refurbish	Discharge Channel - Roc Protection or Gabian	ck FAMP	-	20	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-
Atkinson Dam	Main Wall Embankment	Refurbish	Refurbishment : Repair to rip rap & access road major maintenance - when dam low .		-	-	-	-	-	-	-	-	-	21	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	21	-	-	-
Atkinson Dam	Main Wall Embankment	Refurbish	Refurbishment : Repair to rip rap & access road major maintenance - when dam low .		-	-	-	-	-	-	-	-	-	-	21	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	21	-	-
Atkinson Dam	Observation Bores (15)	Replace		Est								75																									
Atkinson Dam	Hydraulic Piezometer System	Replace		DW Val 2010								7.5										112															
Atkinson Dam	Pressure Relief Wells (19)	Replace		Workshop	-	-	-	-		-	-	20		-	-					-	-	112	-	-	-		-	-		-	-	-			-	-	-
Atkinson Dam	Piezometer Huts	Replace		DW Val 2010	-	-	-	-		-	-	20		-	-					-	-	-	-	-	-		-	-		-	-	-			-	-	-
Atkinson Dam	Telemetry	Replace		DW Val 2010 DW Val 2010	-	-	-	-	25	-	-	20		-	-				25	-	-	-	-	-	-		-	-	25	-	-	-			-	-	-
Atkinson Dam	Water Level Recorder	Replace		DW Val 2010					-										-										21								
Atkinson Dam	Outlet Works Switchboard	Replace		FAMP						15		-		-					-	-		-					-	-	-								
Atkinson Dam	Main Building Switchborad	Replace		FAMP	-					13	30	-		-					-	-		-					-										
LI Distribution	Buaraba Creek Channel	Refurbish	Desilt channel	Bus Case	-	-	-	-	-	-	-	-	-	12	-	-	-	-	-	-	-	-	-	12	-	-	-	-	-	-	-	-	-	12	-	-	-
LI Distribution	Brightview Channel Rising Main Flow Mete	er Replace	-	Static Asset Data	_	_	_	_	_	_			12	_	_	_	_	_	_	_	_	_	_	_	_	_	_	_	_	_	_	_	_	_	_	_	_
	At 207.30M																																				
LI Distribution	Buaraba Creek Supply Pipeline Air Valve 1 At 24.40M	Replace	-	Static Asset Data	-	-	-	-	6	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-
LI Distribution	Buaraba Creek Supply Pipeline Air Valve 2	Replace	-	Static Asset Data	-	-	-	-	6	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-
LI Distribution	At 1770.30M Buaraba Creek Supply Pipeline Double Air	Replace	-	Static Asset Data	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-
LI Distribution	Valve 1 At 1551.40M Buaraba Creek Supply Pipeline Pipework	Replace	-	Static Asset Data	_	_	_	_	_	_	_	_	_	_	_	_	_	_	_	_	_	_	_	_	_	_	_	_	_	_	_	_	_	_	819		_
	(Rising Main Only)																								22										013		
LI Distribution	Buaraba Creek Supply Pipeline Sluice Valve 1 At 259.10M	e Replace	-	Static Asset Data	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	22	-	-	-	-	-	-	-	-	-	-	-	-
LI Distribution	Buaraba Creek Supply Pipeline Valve At 1237.50M	Replace	-	Static Asset Data	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	11	-	-	-	-	-	-	-	-	-	-	-	-
Ll Distribution	1237.50M Brightview Channel Earthworks	Refurbish	Refurbish Channel Banks:- Sandstone country - piping erosion of road and bank.	DCE	-	-	-	66	-	-	-	-	66	-	-	-	-	66	-	-	-	-	66	-	-	-	-	66	-	-	-	-	66	-	-	-	-
LI Distribution	Brightview Channel Fencing	Refurbish	50% of Total Cost (shared with adjacent landowners)	DCE	47	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	47	-	-
LI Distribution	Brightview Channel Grids And Gates	Replace	-	Static Asset Data	_	_		_		_		7	_		_		-				_				_		_	-				_	_				_
LI Distribution	Brightview Channel Access Road	Replace	-	Static Asset Data		-	-	-	_	-		-	-	-	-	-	-	-	-	-	-	-	-	-	-		-	-	_	-	-	_	- 77	_	-	-	-
LI Distribution	Brightview Channel Scour Valve At 2263.11		-	Static Asset Data		-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	23	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-
	<u> </u>																					-															
LI Distribution	Brightview Weir Embankment	Replace	-	Static Asset Data	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	2158	-	-
LI Distribution	Brightview Weir Protection Works	Replace	-	Static Asset Data	-	-	-	-	-	-	-	-	-	267	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-

Part	2/33 2033/34 2034/35 2035/36 2036/37 2037/38 2038/39 2039/40 2040/41 2041/42 2042/43 2043/44 2044/45 2045/46 204
Descriptions   Conground Columnia Col	30 30 30
Statistical Control	
New Total Control New York State   10   10   10   10   10   10   10   1	
Mochanish   Moch	
10000   100000   100000   100000   100000   100000   10000   10000   10000   10000   10000   10000   10000   10000	- 86 86 86
Distribution   Dist	40 40
Distribution   Distribution   Distribution   Distribution   Mississee Pump Station Control Building   Septice   State Asset Data   State Asset D	
Distribution   Aktinson Pump Station Control System   Replace   Static Asset Data	
Distribution   Alkinson Pump Station Autodialer   Replace   Static Asset Data	
Distribution   Abinson Pump Station Autorialized   Replace   Static Asset Data   Sta	30
Distribution   Atkinson Pump Station Flowmeter   Replace   Workshop   Static Asset Data   Static Asset D	16
Raitered	15
Distribution   Atkinson Pump Station Pump Unit 1   Refurbish   Replace   Static Asset Data   Static Asse	53
Aktinson Pump Station Actuator, Elec Rotork ID Istribution Aktinson Pump Station Motor, 75Kw Elec Tyco ID Istribution Aktinson Pump Station Motor, 75Kw Elec Tyco ID Istribution Aktinson Pump Station Pump, Tyco Aktinson Pump Station Motor Replace Static Asset Data Aktinson Pump Station Motor Replace Addisson Pump Station Motor Replace Aktinson Pump Station Motor Replace Static Asset Data Static Asset Data Aktinson Pump Station Motor Replace Addisson Pump Station Pump, Tyco Aktinson Pump Station Motor Replace Static Asset Data Static	
Rotork  Aktinson Pump Station Motor, 75Kw Elec Tyco  Distribution Aktinson Pump Station Pump, Tyco Replace  Static Asset Data  Obstribution Aktinson Pump Station Pump Dint 2  Refurbish  Workshop  Aktinson Pump Station Nalwe Replace  Static Asset Data  Aktinson Pump Station Nalwe Replace  Static Asset Data  Static Asset Data  Aktinson Pump Station Nalwe Replace  Static Asset Data  Static Ass	
Distribution   Alkinson Pump Station Motior, 75kw Elic   Replace   Static Asset Data	12
Alkinson Pump Station Pump, Tyco Replace Distribution Alkinson Pump Station Pump Unit 2 Refurbish Normal Alkinson Pump Station Pump Unit 2 Refurbish Normal Alkinson Pump Station Pump Unit 2 Refurbish Normal Alkinson Pump Station Native Replace Replace Static Asset Data Distribution Alkinson Pump Station Native Replace Static Asset Data Static Asset Dat	
Distribution   Alkinson Pump Station Mayle   Replace   Static Asset Data   Static As	54
Alkinson Pump Station Valve Replace - Static Asset Data	
Distribution   Atkinson Pump Station Motor   Replace   Static Asset Data	
Distribution   Sippels Weir - 23.8Km   Refurbish   Refurbish   Refurbish   Butterfly - 200mm   20yr PW   -	15 -
Al Distribution Sippels Weir Outlet Valve Refurbish Puter Feplace @ 10 years interval-actual cost   Sover Mile Lagoon Diversion Channel Industribution   Seven Mile Lagoon Diversion Channel   Refurbish   Seven Mile Lagoon Diversion Channel   Replace   Static Asset Data   Seven Mile Lagoon Diversion Channel   Replace   Seven Mile Lagoon Diversion Channel	13 -
1568M   Including Desilt of Reg   Structure	
Fencing (shared with adjacent landowners)  LI Distribution Seven Mile Lagoon Diversion Channel Grids Replace - Static Asset Data 3	- 20 20 20
And Gates  I Distribution Seven Mile Lagoon Diversion Channel Replace - 20yr PW 27	
l Distribution Seven Mile Lagoon Diversion Channel Replace - 20yr PW 27	
Program	16 16 16 16 16 16 16 16 16 16 16 16 16 1
	115 155 16 26 82 165 203 31 172 226 119 3184 44 62