

Irrigation Infrastructure Renewal Projections - 2013/14 to 2046/47

Report - Lower Lockyer Tariff Group



© Queensland Bulk Water Authority 2012

This document is and shall remain the property of Queensland Bulk Water Authority. The document may only be used for the purposes for which it was prepared. Unauthorised use of this document in any form whatsoever is prohibited.

Document Status

Version	Date	Author	Reviewed	PCG Approval
1	20/4/12	AL/GH	MD	
2	23/4/12	GH		



Contents

1.	Intro	duction	1	4
2.	Ass	et Infori	mation	5
	2.1	Irrigati	on Infrastructure	5
	2.2	Releva	ant Asset Information	5
3.	Proj	ections		7
	3.1	Summ	ary	7
	3.2	Signifi	cant Projects	7
	3.3	Additio	onal Commentary	9
Tal	ole In	dex		
	Tabl	e 1	Summary of Irrigation Infrastructure	5
	Tabl	e 2	Significant Projects	7
	Tabl	e 3	Summary of Renewal Projections	8

Appendices

- Water Supply Scheme Schematic
- В Renewal Projections



1. Introduction

Seqwater owns and operates the following seven irrigation schemes:

- Central Lockyer WSS;
- Lower Lockyer WSS;
- Logan River WSS;
- Mary River WSS;
- Cedar Pocket WSS;
- Warrill Valley WSS; and
- Central-Brisbane WSS.

Segwater also owns and operates a distribution system, the Morton Vale Pipeline.

There are nine tariff groups associated with these schemes.

To assist with the determination of price paths, a forecast of future renewal expenditure is required at the individual tariff group level.

The renewal projections have been developed, in accordance with the scope and methodology separately documented in the Methodology report. The projections have been developed in separate reports, one for each tariff group.

This report outlines the projections for the Lower Lockyer Tariff group. It should be read in conjunction with the Methodology report.



2. Asset Information

2.1 Irrigation Infrastructure

A summary of Seqwater's irrigation infrastructure facilities and assets is provided in **Table 1** below.

Table 1 Summary of Irrigation Infrastructure

WSS Scheme	Tariff Group	Dams	Weirs	Off-Stream Storage	Other Key Assets
Lockyer	Lower	NA	Brightview Weir, Buaraba Creek Weir, O'Reilly Weir, Potters Weir, Sippels Weir	Atkinson Dam	Buaraba Creek Channel, Brightview Channel Rising Main, Buaraba Creek Supply Pipeline, Brightview Channel, Buaraba Creek Diversion Channel, Gauging Stations, Observation Bores, Atkinson Pump Station, Seven Mile Lagoon Diversion Channel, Flowmeters

A schematic drawing of the scheme is provided in Appendix A.

2.2 Relevant Asset Information

The following existing information was reviewed and where relevant, utilised to develop the renewal projections:

- Asset Register
- Annual, 5 Year and Comprehensive Dam Safety Reviews and Assessments
- Dams Weirs Valuations 2010
- Water Meter Upgrade Plan
- Draft WSS 20 Year Programme of Work 2008/09 2028/29
- 2011 Site Safety Assessments





- Extracts from Financial Asset Register
- ▶ 2009 Asset Valuation Cardnos
- ▶ 2010 Asset Valuation Dams & Weirs Cardnos
- ▶ Atkinson Dam Facilities Asset Management Plan (FAMP) 2012

Filename: Seqwater_IrrigRen_Tariff Group Summary_LLO_Ver 2



3. Projections

3.1 Summary

A summary of the renewal and refurbishment projections for the period 2013/14 - 2046/47 is provided in Table 3.

Further details are provided in Appendix B.

It should be noted that all values are in \$2012-13.

3.2 Significant Projects

A list of projects that come under one of the following categories are outlined in Table 2 below:

- ▶ Scheduled between 2013/14 and 2016/17 financial years and having a project value greater than the average project value for that period; and
- A project that has an impact on the annuity of greater than 10%.

Table 2 Significant Projects

Asset	Description of Work	Timing of Work	Project Value	Signif.*
Potters Weir	Rehabilitation to repair scour bypass of weir	2013/14	\$60k	HAV
Sippels Weir	Rehabilitation to repair scour bypass of weir	2013/14	\$72k	HAV
Brightview Weir	Rehabilitation of embankment	2043/44	\$2070	IA
Brightview Channel	Desilting	2016/17	\$66k	HAV
Brightview Channel	Replacement of fencing (50% shared with adjacent landowners)	2013/14	\$47k	HAV

Notes: *Significance: HAV – Higher than Average Value (for period from 2013/14 to 2016/17) IA – Project has an impact on the annuity of greater than 10% (refer Section 3.3 for commentary)



 Table 3
 Summary of Renewal Projections

Parent Asset		Expenditure Forecast Each Year (\$k) 2013/14 2014/15 2015/16 2016/17 2017/18 2018/19 2019/20 2020/21 2021/22 2022/23 2023/24 2024/25 2025/26 2026/27 2027/28 2028/29 2029/3																
		2013/14	2014/15	2015/16	2016/17	2017/18	2018/19	2019/20	2020/21	2021/22	2022/23	2023/24	2024/25	2025/26	2026/27	2027/28	2028/29	2029/30
Atkinson Dam Lower Lockyer		40	20	-	-	60	15	30	125	22	21	21	-	-	-	45	-	45
Distribution		206	-	-	66	43	141	-	10	78	349	106	-	-	93	77	141	-
Water Flowmeters		-	-	-	-	-	-	-	-	-	-	-	-	32	32	32	32	32
	Total	246	20	-	66	103	156	30	135	100	370	127	-	32	125	154	173	77

Parent Asset								Expe	nditure F	orecast l	Each Yea	r (\$k)						
	·	2030/31	2031/32	2032/33	2033/34	2034/35	2035/36	2036/37	2037/38	2038/39	2039/40	2040/41	2041/42	2042/43	2043/44	2044/45	2045/46	2046/47
Atkinson Dam Lower Lockyer		112	217	5	-	-	10	-	66	-	-	154	-	21	31	-	-	-
Distribution		59	66	94	139	-	-	66	83	187	15	2	210	82	3,137	28	46	66
Water Flowmeters	.=	32	32	32	32	32	32	32	32	32	32	32	32	32	32	32	32	32
Т	otal	203	315	131	171	32	42	98	181	219	47	188	242	135	3,200	60	78	98



3.3 Additional Commentary

Commentary on projects that have a higher than average project value includes:

- Repair of scour bypass of Potters Weir by installing sheet pile wall to stop significant leaking.
- Repair of scour bypass of Sippels Weir by installing sheet pile wall to stop significant leaking.
- De-silting of Brightview Channel including repair of drainage benches to ensure efficient transfer of water.
- ▶ Replacement of 4km of boundary fencing along Brightview Channel. Cost is 50% of total cost due to cost sharing with adjacent landowners.

The following commentary is provided on the Brightview Weir embankment rehabilitation project listed in Table 2 as having an annuity of greater than 10%:


▶ The renewal work has been forecasted for when the embankment is considered likely to reach the end of its useful life based on its age and typical useful asset life. The cost estimate shown is based on the replacement cost from the asset valuation data. The renewal work will most likely comprise of rehabilitation of the embankment and be less than the cost of replacement.

For the forecasted renewal expenditure between 2013/14 and 2016/17, values were compared with Sunwater's renewals projections which were the basis of the SunWater irrigation prices for 2006/07 to 2010/11. When excluding the water meter upgrade costs which will be excluded from the annuity, it was noted the total value of Seqwater's renewal forecast was approximately 130% of Sunwaters. The difference is believed to be primarily due to:

- Seqwater projections being based on more up-to-date information.
- Seqwater projections include more expenditure on distribution infrastructure including the repair of Potters and Sippels Weirs.



Appendix A Water Supply Scheme Schematic





Appendix B Renewal Projections

Parent Asset	Asset Details Asset Description	Works	Renewal Detail: Comments	S Costing Source	2013/14 20	114/15 20:	15/16 201	6/17 201	17/18 201	8/19 201	19/20 20	120/21 20	121/22 20	122/23 20	23/24 20	024/25 20:	25/26 20	26/27 202	Expe	enditure 28/29 202	Forecast	Each Yea 0/31 203	ar (\$k) 1/32 203	2/33 203	3/34 203	4/35 203	5/36 203	6/37 203	17/38 203	8/39 203	9/40 204	0/41 204	1/42 2042	2/43 2043	3/44 2044	4/45 204	i/46 2046/4
		Description	1																				110														
Atkinson Dam Atkinson Dam	Office Building General Storage	Replace Replace	-	Static Asset Data Static Asset Data	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	110 47	-	-	-	-	-	-	-	-	-	-		-	-	-
Atkinson Dam	Project Storage	Replace	_	Est Data		- 1		-		-													30			- 1	-					-					-
Atkinson Dam	Core Shed/Storage	Replace	_	Est			-	-	-	-	_	-	_	-	-	-	_	-	_	_	_	_	30	_	_	_	_	_	_	-	_	-	-	_		_	-
Atkinson Dam	Fencing	Replace		Buss Case 2012	10		-	-		-		-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	10	-	-
Atkinson Dam	Outlet Works To Pstn	Refurbish	Refurbish metal items	20yr PW		-	-	-	-	-	-	10	-	-	-	-	-	-	-	-	-	-	-	-	-	-	10	-	-	-	-	-	-	-		-	-
			and install kickboards around handrails																																		
Atkinson Dam	Bulkhead Gate	Replace		20yr PW		-	-	-	5	-	-	-	-	-	-	-		-		-	-	-		5	-		-		-	-		-	-	-		-	-
Atkinson Dam	Monorail & 1 Tonne Crane	Replace		DW Val 2010	-	-		-	-	-	-		-		-		-	-	_	-	-	-	-	-	-	-	-	-	-	-	-	11	-	-			
Atkinson Dam	Trash Screens	Replace	-	DW Val 2010	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	116	-	-	-	-	-
Atkinson Dam	Trash Screens	Replace		20yr PW	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	45	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-
Atkinson Dam	Valve, 914Mm Butf	Replace	-	DW Val 2010	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	27	-	-	-	-	-
Atkinson Dam	Valve, 914Mm Butf	Refurbish	Assess in advance and then refurbish as required	20yr PW	-	-	-	-	10	-	-	-	-	-	-	-	-	-	10	-	-	-	-	-	-	-	-	-	10	-	-	-	-	-	-	-	-
Atkinson Dam	Valve, 914Mm Butf	Refurbish		20yr PW				_		_			22	_										_	_		_			_		_	_				
Atkinson Dam	Access Roads And Carpark	Refurbish	Roadwork - seal road	FAMP				_	10	_				_										_	_		_			_		_	_				
Atkinson Dam	Spillway Control Structure	Refurbish	Sluice Gate 1 Assembly -		15				-																												
			Gate unable to be opened. Gear box and gate to be repaired.																																		
Atkinson Dam	Spillway Control Structure	Refurbish	Sluice Gate 2 Assembly - Gate unable to be opened. Gear box and gate to be repaired.	FAMP	15	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-
Atkinson Dam	Spillway Control Structure	Refurbish	Discharge Channel - Rock Protection or Gabian	c FAMP	-	20		-	-	-	-	-	-	-	-		-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-		÷
Atkinson Dam	Main Wall Embankment	Refurbish	Refurbishment : Repair to rip rap & access road major maintenance - when dam low .	20yr PW	-	-	-	-	-	-	-	-	-	21	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	21	-	-	-
Atkinson Dam	Main Wall Embankment	Refurbish	Refurbishment : Repair to rip rap & access road major maintenance - when dam low .		-	-	-	-	-	-	-	-	-	-	21	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	21	-	-
Atkinson Dam	Observation Bores (15)	Replace		Est								75																									-
Atkinson Dam	Hydraulic Piezometer System	Replace	•	DW Val 2010	-	-	-	-	-	-	-	/5	-	-	-	-	-	-	-	-	-	112	-	-	-	-	-	-	-	-	-	-	-	-	-	-	
Atkinson Dam	Pressure Relief Wells (19)	Replace	-	Workshop	-	-	-	-	-	-	-	20	-	-	-	-	-	-	-	-	-	112	-	-	-	-	-	-	-	-	-	-	-	-	-	-	
Atkinson Dam	Piezometer Huts	Replace	•	DW Val 2010	-	-	-	-	-	-	-	20	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-
Atkinson Dam	Telemetry	Replace	•	DW Val 2010	-	-	-	-	35	-	-	20	-	-	-	-	-	-	25	-	-	-	-	-	-	-	-	-	25	-	-	-	-	-	-	-	-
Atkinson Dam	Water Level Recorder	Replace	-	DW Val 2010 DW Val 2010	-	-	-	-	35	-	-	-	-	-	-	-	-	-	33	-	-	-	-	-	-	-	-	-	21	-	-	-	-	-	-	-	-
Atkinson Dam	Outlet Works Switchboard	Replace	•	FAMP	-		-	-	-	15	- 1	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	21	-	-	-	-	-	-	-	-
Atkinson Dam	Main Building Switchborad	Replace		FAMP		-				-	30						- 1			-					-		-						-				-
LI Distribution	Buaraba Creek Channel	Refurbish	Desilt channel	Bus Case	-	-	-	-	-	-	-	-	-	12	-	-	-		-		-	-	-	12	-	-	-	-	-	-	-	-		12	-	-	-
LI Distribution	Brightview Channel Rising Main Flow Mete At 207.30M	er Replace	-	Static Asset Data	-	-	-	-	-	-	-	-	12	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-
LI Distribution	Buaraba Creek Supply Pipeline Air Valve 1 At 24.40M		-	Static Asset Data	-	-	-	-	6	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-
I Distribution	Buaraba Creek Supply Pipeline Air Valve 2 At 1770.30M Buaraba Creek Supply Pipeline Double Air		=	Static Asset Data Static Asset Data	-	-	-	-	6	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-
.l Distribution	Valve 1 At 1551.40M Buaraba Creek Supply Pipeline Pipework		- -	Static Asset Data	-																														819		-
LI Distribution	(Rising Main Only) Buaraba Creek Supply Pipeline Sluice Valve 1 At 259.10M	Replace	-	Static Asset Data	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	22	-	-	-	-	-	-	-	-	-	-	-	-
l Distribution	Buaraba Creek Supply Pipeline Valve At 1237.50M	Replace	Ē	Static Asset Data	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	11	-	-	-	-	-	-	-	-	-	-	-	-
Distribution	Brightview Channel Earthworks	Refurbish	Refurbish Channel Banks:- Sandstone country - piping erosion of road and bank.	DCE	-	Ē	-	66	-	-	Ē	-	66	-	÷	-	Ē	66	-	-	-	Ē	66	Ē	-	Ē	-	66	-	÷	Ē	÷	66	=	-	-	- 6
I Distribution	Brightview Channel Fencing	Refurbish	50% of Total Cost (shared with adjacent landowners)	DCE	47	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	47	-	-
LI Distribution	Brightview Channel Grids And Gates	Replace	-	Static Asset Data				-	-	-	-	7	-	-		-	-		-		-	-	-	-	-	-	-	-	-	-	-	-	-			-	
LI Distribution	Brightview Channel Access Road	Replace	-	Static Asset Data	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	77	-	-	-	-
LI Distribution	Brightview Channel Scour Valve At 2263.1N	M Replace	-	Static Asset Data		-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	23	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-
LI Distribution LI Distribution	Brightview Weir Embankment Brightview Weir Protection Works	Replace Replace	-	Static Asset Data Static Asset Data	-	-	-	-	-	-	-	-	-	267	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	- :	2158	-	-

Parent Asset	Asset Details Asset Description	Works Description	Renewal Details Comments	Costing Source	2013/14 20	14/15 201	5/16 2016	/17 2017	/18 2018/	19 2019/	20 2020/2	1 2021/22	2022/23	2023/24 20	024/25 202	25/26 202	6/27 202			orecast E /30 2030/			3 2033/3	4 2034/3	2035/36	2036/37	2037/38	2038/39	2039/40 20	140/41 20	41/42 2042	/43 2043	/44 2044/4	45 2045/	46 2046/4
l Distribution	Buaraba Ck Diversion Channel Earthworks		Refurbish: Channel side slope erosion/piping in fill areas - stabilisation with road base - Costs (\$5.5K & \$15.9K incorrect)- work put off from 03 for Aitkinson	Bus Case	-	-	-	-	30	-	-	-	- 30	-	-	-	-	30	÷	-	-		30	-			- 30	-	-	-	-	30	-	-	-
.l Distribution	Buaraba Ck Diversion Channel Gate Control	Replace	-	Static Asset Data		-	-	-	-	-	-	-		-	-	-	-	12	-	-	-	-	-	-				-	-	-	-	-	-	-	-
LI Distribution	Equipment Buaraba Ck Diversion Channel Solar Panel	Replace		WORKSHOP		-		-	-		-					-		5			-			-				-		-	-	-		-	
LI Distribution	Buaraba Creek Weir Valve, 400Mm Gate Keystone	Replace	-	Static Asset Data	-	-	-	-	-	-	-	-		-	-	-	-	-	-	-	-	-	-	-				-	-	-	-	-	-	-	20
LI Distribution	Observation Bores	Refurbish	Bore replacement program - Replace 40% of bores, every 10 years	Workshop - 31 Jan 2012	-	-	-	-	-	86	-	-		86	-	-	-	-	86	-	-	-	- 8	86				86	-	-	-	-	86	-	-
LI Distribution	Gauging Stations-Lower Lockyer	Replace		Workshop - 31 Jan 2012	-	-	-	-	-	-	-	-	- 40	-	-	-	-	-	-	-	-	-	40	-				-	-	-	-	40	-	-	-
LI Distribution LI Distribution LI Distribution	O'Reilly Weir R/Bank Access Road Potters Weir Structure Atkinson Pump Station Control Building	Replace Refurbish Replace	Repair scour bypass	Static Asset Data DCE Static Asset Data	60	-	:	-		:		-		-	-	-	-	-	30		36		-	-				-	-	-	-	-	-	-	-
LI Distribution LI Distribution	Atkinson Pump Station Control System Atkinson Pump Station Autodialler	Replace Replace		Est Static Asset Data	-	-	-	-		-	-				-	-	-	-		-	-		-	-				30 16		-	-	-	-	-	-
LI Distribution LI Distribution	Atkinson Pump Station Flowmeter Atkinson Pump Station Switchboard, Raicrest	Replace		workshop Static Asset Data	-	-	-	-	-	-	-	-		-	-	-	-	-	-	-	-	-	-	-			- 53	-	15	-	-	-	-	-	-
LI Distribution	Atkinson Pump Station Pump, 25Mm Sump	Replace	-	workshop	-	-	-	-	-	-	-	-		-	-	-	-	-	-	-	-	-	-	-				-	-	2	-	-	-	-	-
LI Distribution LI Distribution	Atkinson Pump Station Pump Unit 1 Atkinson Pump Station Actuator, Elec Rotork	Refurbish Replace	-	workshop Static Asset Data	-	-	-	-	-	-	-	-		-	-	-	-	30	-	-	-	-	12	-				-	-	-	-	-	-	-	-
LI Distribution	Atkinson Pump Station Motor, 75Kw Elec Tyco	Replace	-	Static Asset Data	-	-	-	-	-	-	-	-		-	-	-	-	-	-	-	-		-	-				-	-	-	13	-	-	-	-
LI Distribution LI Distribution	Atkinson Pump Station Pump, Tyco Atkinson Pump Station Pump Unit 2	Replace Refurbish	-	Static Asset Data workshop	-	-	-	-	-	-	-	-		-	-	-	-	-	-	-	-	-	-	-				- 20	-	-	54	-	-	-	-
LI Distribution	Atkinson Pump Station Valve			Static Asset Data			-	- 1		30		-	: :	- 1		- 1		-		- 1	-							30	- 1	- 1			-	-	26
LI Distribution	Atkinson Pump Station Motor			Static Asset Data	-	-	-	-	-	-	-	-		-	-	-	-	-	-	-	-	-	-	-				-	-	-	-	-	-	15	
LI Distribution	Atkinson Pump Station Valve	Replace	-	Static Asset Data		-	-	-	-	-	-	-		-	-	-	-	-	-	-	-	-		-				-	-	-	-	-	-	13	-
LI Distribution LI Distribution	Sippels Weir - 23.8Km Sippels Weir Outlet Valve	Refurbish Refurbish		DCE 20yr PW	72	-	-	-	-	5	-	-		-	-	-	-	-	5	-	-	-	-	-				5	-	-	-	-	-	-	-
LI Distribution	Seven Mile Lagoon Diversion Channel 1568M	Refurbish	Refurbish: Desilt Channel including Desilt of Reg Structure	Bus Case 2012	20	-	-	-	-	20	-	=		20	-	-	=	-	20	-	-	-	- :	20				20	-	-	-	-	20	-	-
LI Distribution	Seven Mile Lagoon Diversion Channel Fencing	Refurbish	50% of Total Cost (shared with adjacent landowners)	Bus Case 2012	7	-	-	-	-	÷	-	-		-	-	-	÷	-	-	-	-	-	÷	-				-	-	-	-	Ē	7	-	-
LI Distribution	Seven Mile Lagoon Diversion Channel Grids And Gates	Replace	-	Static Asset Data	-	-	-	-	-	-	-	3		-	-	-	-	-	-	-	-	-	-	-				-	-	-	-	-	-	-	-
LI Distribution	Seven Mile Lagoon Diversion Channel Regulating Structure	Replace	•	20yr PW	-	-	-	-	-	-	-	-	-	-	-	-	27	-	-	-	-	-	-	-				-	-	-	-	-	-	-	-
Water Flow Meters		Replace	Replace batch of 9 meters each year	Est	-	-	-	-	-	-	-	-		-	-	32	32	32	32	32	32	32	32	32 3	2 32	3	2 32	32	32	32	32	32	32	32	32
				Tota	1 246	20	0	66	103	156	30 1	35 10	0 370	127	0	32	125	154	177	77	202	215 1		71 2	2 42	9:	8 181	219	47	188	242	125 2	2200	60	78